



ナレッジベース > easYgen-3000XT > LSG not recognizing easYgen-3000XT in firmware 2.10, 2.10-1 & 2.10.2

LSG not recognizing easYgen-3000XT in firmware 2.10, 2.10-1 & 2.10.2

Clemens - 2024-09-27 - easYgen-3000XT

In easYgen-3000XT release 2.10, 2.10-1, 2.10-2 the LSG load share gateway was not recognized.

Please upgrade your easYgen-3000XT controls to latest corrected firmware you can download here:

<https://wss.woodward.com/manuals/Support/Forms/AllItems.aspx>