



[Knowledgebase](#) > [RP-3000XT](#) > [HMI Deltas of RP-3000XT versus easYview HMI panel](#)

HMI Deltas of RP-3000XT versus easYview HMI panel

Clemens - 2024-09-13 - [RP-3000XT](#)

RP-3000XT in field can be replaced by easYview panels configured for VNC HMI mode.

Keep in mind that the easYview navigation bar on the left side cannot be removed

